

76. 13.
The Metallurgical Treatment
of an Argentiferous Galena from
Burleigh Tunnel, Colorado
By
Samuel James
Cambridgeport Mass

Metallurgical Treatment
of an Argentiferous Saliva from
Burlingame Tunnel, Colorado.

Samuel James Jr

Mass. Inst. Tech.

1876.

Metallurgical Treatment of an Argentiferous Galena from Burdigh Tunnel, Colorado.

The tunnel from which this ore comes, is worked by a company of Massachusetts capitalists into the base of Sherman mt. near Georgetown Colorado. It is run for the purpose of discovering new lodis of ore, and affording drainage and transportation of material to veins now being worked. The location is on the valley of Clear Creek on the South Pass of the mountain, about three miles from Georgetown. A number of tunnels have been started but few of them seem to be much value on account of the amount of worthless rock that has to be taken out before ore is reached. In 1871 the tunnel had been driven 1200 feet at the rate of 500 feet per year, being 8 ft. wide by 8 ft., and rises one foot in two hundred. It is nearly at right angles to the outcropping veins.

Since 1871 the tunnel has been driven to 1830 feet from the entrance through

2.

Solid rock, and has cut five lodes, the ore taken from four exceeds in value that taken from mine. One lode 1700 ft. from the portal measures 16 ft. wide and assays 70 oz. of silver to the ton.

Mr. Burleigh thinks that they will soon strike richer lodes, and so is shipping improved machinery in order to double the rate of running the tunnel.

Mr. Lincoln, who visited the place in 1841, says that the country rock is granitic, quartz and feldspar are found alone, and all varieties of proportions in combination. Pure hornblende is also found in large deposits.

The ore had to work ^{came} from Lode No. 2 (situated about 900 feet in the tunnel) which is 13 ft. wide, dipping 69° with a strike $N 30^\circ W$, containing ^{in streaks} ore an inch or two in width. The ore is an argentiferous galena, having zinc blende of a dark yellowish color and crystalline structure. Besides this zinc blende are pyrite, quartz, feldspar, chalcopyrite and traces of mica.

The ores of that region are mostly auriferous near the surface, but the silver seems to increase and gold disappear as you go down. This ore has no antimony or arsenic which is of advantage, since these two metals are of great trouble in working. The ore assays ^{\$}35.73 per ton that is 27.7 oz. at 129 per oz. of silver, and has 61.37 lbs of lead, which is 1227.4 lbs per ton.

On account of the high price of transportation and working, this does not afford a profit in that region. The lead also is not of value there, but when there are means of getting it to the States cheaply it will make this a desirable ore. This lead at six cents per pound is worth \$73.64.

A mineral analysis of this ore gives:

	Zinc Blende ^(ZnS)	8.32
The galena was	Galena (PbS)	70.86
both coarse and	Pyrite (FeS)	12.04
fine grained, the	Chalcopyrite	1.53
pyrite was fine	Quartz (SiO ₂)	6.95
grained.	Feldspar	98.70

The ore was principally in large pieces.

I made two determinations of the ore as follows.

Sulphur	20.56	20.67	Average 20.61
Lead	61.48	61.27	61.37
Zinc	5.54	5.62	5.58
Bron	6.06	6.09	6.07
Copper	.49	.56	.52
Galena	5.96	5.94	5.95
Silver	.095	.095	.095
	<u>100.185</u>	<u>100.245</u>	<u>100.195</u>

The amount of ore I had to work with was 12 ⁷/₁₆ lbs. This was crushed in a 5 by 2 ¹/₂ Blake crusher to the size of a walnut, and then put through a pair of rolls until it passed through a ¹/₂ inch sieve. The loss in doing this was 16 ⁷/₁₆ lbs, and it took (not counting stops for accidents) two hours and fifty three minutes. Before crushing it was broken into pieces the size of one fist, and samples of the minerals taken.

In order to analyse a type sample of the ore, I put the whole through a sampler and saved out 2 ¹/₂ lbs. The sampler used was made of two (one) sheet iron cones with their apices adjoining. The top one had a hole in the apex the size of a cent

through which all the ore fell onto the lower cone. The lower cone had four slits in it, under which were four boxes to catch the ore that fell through, and as only a fraction fell through the slits, that was taken as a sample. A lot of ore was saved here for the blast furnace run, and so I really had $\frac{1274 \frac{5}{16}}{174 \frac{5}{16}}$ eleven hundred pounds to use.

Sample $21 \frac{1}{2}$
 For blast furnace $13 \frac{1}{2}$
 Lost $16 \frac{1}{16}$
 $174 \frac{5}{16}$

If this ore were smelted as it now stands it would be an expensive operation for the sulphide of lead is more volatile than the sulphate or oxide (which we get by roasting), and the amount of sulphur to be worked off would require a large amount of flux, so that in practice it is rarely smelted as galena.

Now we have to get rid partly of the sulphur, not wholly since that would be hard on account of the stability of sulphate of lead. When the galena is heated at a low temperature, it is converted into oxide and sulphate, the oxide being volatile causes a loss, while the sulphate is quite permanent. Zinc blende is also reduced to oxide.

A long red flame, spreading over the ore affords the heat to drive off the sulphur, but not agglomerate the ore, if well stirred. For stirring, iron hoes with long handles are used, every five minutes or so.

The ore was charged in lots of 85 pounds each, both furnaces having the same sized charge, and were run $3\frac{1}{2}$ hours on each lot. One man was allowed to a charge at each furnace, and the run lasted from two o'clock on Wednesday, when a charge was put into the long furnace, until six o'clock Thursday when both furnaces were emptied.

During this time thirteen charges were used, the long furnace running $2\frac{1}{2}$ hours, and the hollow bed $2\frac{1}{2}$ hours. To do this in the reverberatory with the hollow bed, 358 lbs of bituminous coal were used on 510 lbs of galena, and in the long furnace 296 lbs of coal were used on 590 lbs of ore; that is, one pound of galena was roasted four hours by 0.59 pounds of coal.

The loss in weight was $1100 - 656 = 444$ lbs.

No of charges		Coals	Time
Long	H.P. Furnace		
1		69 3/8	4 hours
	2	52 3/4	3-40
3		22 3/4	4
	4	83 3/4	3-45
5		31 1/2	3-40
	6	27 1/2	3-55
7		49 1/4	3-50
	8	58 3/8	4
9		36 1/8	3-55
	10	77	3-50
11		53	3-50
	12	59	3-35
13		34	3-45

654 1/8 3.49 av.

In the hollow
 but the charges used
 59 ³⁵/₄₈ lbs of coal each,
 and in the long 42 ⁵/₁₆.
 The sulphur in
 the roasted product
 9.66 sfo was a loss of
²⁰/_{9.66} 10.95 sfo, but for
^{14.95} each atom of sulphur
 driven off, either one
 atom of oxygen has
 taken its place to form
 oxide, or four combined
 with the sulphur to
 form sulphate, so the
 weight can't be reduced

so very much. The amount of lead in
 the roasted product was, by two analyses,
 58.05 sfo and 58.35, average 58.2, and silver
 by two assays .096 sfo which is 14.76 oz in the
 lot, a loss of 0.48 oz of silver in roasting.

1056.	amt. of lead in raw galena	675.07
58.2	" " " " roasted "	614.59
614.59	Loss " " " " " "	60.48

As this ore was rich in lead and had little silica, the Flintshire process of smelting in the reverberatory to metal matte and slag was tried. In this process the undecomposed Pb is acted on by PbO, and lead separated, and the PbSO₄ is also acted on by PbS and Pb separated, as follows $PbS + 2PbO = 3Pb + SO_2$ and $PbS + PbSO_4 = 2SO_2 + 2Pb$. If much silica were present it would prevent this reaction by the formation of a silicate of lead.

The ores on which this is used, generally have over 75% of lead in them, and often are nearly pure galena. The heat has to be more intense than for roasting, in order to decompose the sulphate, and charcoal, by furnishing carbon to unite with the oxygen, helps break it up. The fire was lit at 2-25^{1/2} o'clock A.M., and at three the fire was 8 inches deep and a good flame on, at 4-45 there was a strong roasting heat and the furnace was ready, but I was not, so my charge was put in until 8-10, and when this was pasty and

lumping powdered coal was added, but in vain, for I could not get enough heat to melt the ore. So I gave up trying to reduce it and only heated to a pasty mass in a few minutes, and withdrew the charge. Other charges were only heated for an hour, and were stirred harder than in roasting, because to keep a fresh surface to the blaze is harder work when the ore is pasty than when dry.

Time Start	Time Stop	Time	Ore	Reagent Coal
8-10	10-55	2-45	132 ⁷ / ₈	10 ¹ / ₄
11	12-45	1-45	123 ⁷ / ₈	10
12-55	1-55	1	185 ⁷ / ₈	
1-10	2-10	1	208 ⁷ / ₈	
3-30	4-30	1	208 ⁷ / ₈	
4-35	5-30	.55	201 ⁵ / ₈	

1156

The amount of coal used for heating was 546 ⁵/₈ lbs.

This was done in the hollow

lead furnace. The total time of agglomerating was 9 hours 20 minutes.

The loss of sulphur was $\frac{966}{652} = 3.14\%$ of lead was, the agglomerated ore having 60.68% of lead in it, there being 996 ¹/₂ lbs of ore, the loss of weight being 996 ¹/₂ - 59 ³/₄ lbs. Some minute pieces of lead were found in this ore, .0125 grms. in 36.1 grms.

The causes of failure seem to be, not enough heat, and the zinc chloride, which with the silica also would make a very

infusible slag, though 10 ops might have been run down perhaps, if a higher heat had been obtained. The slags from this process are rich (having often 55.00 of lead) and are run down in the blast furnace in practice. This was then crushed to the size of a walnut, and placed aside, until it could run the blast furnace.

Blast Furnace.

To get the lead away from the other ingredients of the ore, tap cinder is used. This furnishes iron for the sulphur and silica, the sulphur having a stronger affinity for iron than for lead, the silica combining to a fusible slag which flows off. It is important to add enough tap cinder and not too much, for if an infusible slag is formed, the furnace will be choked up and the operation stopped. The iron takes the place of the lead, or precipitates it, so this is called the iron reduction process.

To know how much cinder

we need, an analysis has to be made, and I got the following results. The cinder is call tap cinder from puddling furnace, and this I used came from the "Bay State Iron Works" in South Boston. As it is

SiO ₂	17.09	16.95	not easy to get this
FeO	72.68	72.76	cinder in the right
S	.54	.61	proportion, limestone
Al ₂ O ₃	5.97	6.16 (6.05)	is added, to partially take
CaO	1.35	1.30	the place of iron, and
P ₂ O ₅	3.82	3.68	magnetite. So these had
	101.45	101.46	to be analysed as follows.

	SiO ₂	FeO	Al ₂ O ₃	CaO	S
Tap Cinder	17.0	72.75	6.06	1.9	.58
Limestone	0.6	0.00	0.0	55.6	0.00
Magnetite	5.75	80.00	-	-	-
Galena	5.95	7.79	-	-	6.52

A slag of silica 30 to protoxide of iron 56, we know is a good one from previous runs, so we try to get that ratio, leaving enough iron to form a matte with the sulphur. First I find the amount of this slag ^{that} exists in the tap cinder, and see how much extra FeO I have for the silica and sulphur of the ore.

30 : 56 :: 17 : x - amt. of Fe used by cinder itself $x = 31.7$ FeO

Therefore $\frac{72.75}{31.7} \cdot 41.05$ sp of the FeO in the cinder is at my disposal. Next I want to know how much Sulphur combines with FeO to form the matte. The atomic weight of the sulphur : the atomic weight of FeO :: one lb. of sulphur : x the weight of FeO required to flux it. $\therefore 32 : 72 :: 1 : x, x = 2.25$ lbs. Now we have in the 1000 lbs. of ore 65.2 lbs. of sulphur, therefore $\frac{65.2}{2.25} = 146.7$ lbs. of FeO are wanted for the sulphur. 41.05 sp of the tap cinder can be used for this, therefore it will take 357.3 pounds of cinder for our matte.

To use up our SiO_2 in the ore, 59.5 pounds $30 : 56 :: 59.5 : x, x = 111.06$ = the amount of FeO wanted to flux the silica of the ore, of this 77.9 lbs are furnished by the ore itself, $\frac{111.06}{77.9} = 33.16$ lbs, then we will get from the cinder $41.05 \cdot \frac{33.16}{80.7}$. The amount of cinder in all is $\frac{357.3}{80.7} = 438$ pounds.

The pounds of SiO_2, FeO, Al_2O_3, CaO the constituents are
 Cinder 74.4 318.6 26.5 8.2 given here.

Ore 59.5 77.9
 Total 133.9 396.5 26.2 8.2 = 564.8 pounds in slag and matte, then subtract the matte, which is 146.7 $\frac{564.8}{146.7} = 418.1$ and we have 418.1 pounds of slag, and calculating the percents from the

weights given, we see how near the wanted slag they come, and then add lime and magnetite to fix them right. I did not have to use any magnetite for I got a good proportion without. Add to the weight of the slag 27 lbs of lime, and we have a weight 445.1 of which 30.08 is SiO_2

This is the calculated slag.

SiO_2	30.05
FeO	56.12
CaO	7.91
MgO	5.89
	100.00

To supply the lime (as there are 55.6 of lime in this marble used) it took $55.6 \times \frac{27}{48.56}$

48.56 lbs of marble. Taking 30 lbs of ore to one charge, dividing the limestone and cinder up proportionately, we have for charge 30 ore, 13 cinder, 1 1/2 limestone, and 10 coke, taken from amount of coke used in previous runs. One pound of galena was also added to act as a fluxifier, just how, I don't know.

Next, the furnace is a small cupola, being 4 ft. 9" from bottom to feed door, the walls are 1 foot thick and are lined with fire brick on the inside. The inside measures 11 in. by 11 in.

The feed door is 11 in by 1 ft. 3 in and the front is 11 in by 1 ft 11 in. The very bottom of the inside shaft ^{has} a bed of broken chips of fire brick firmly pounded down to a thickness of 5 inches and on this, layers of brasse are pounded, and hardened by a red hot iron. The layers are built up until the top is 12 inches from the bottom of the shaft, when a basin is scooped out approaching the sides and back until within an inch, being 3" deep in front, and sloping upward at the back, to the level of the top. A channel is cut, leading out to the front, and then the front is bricked up.

Only the small channel runs out of the furnace, and it was expected that the ore would be reduced in the lower part of the furnace, and the metal, matte, and slag run into the basin, the slag being lighter would float, and as soon as the basin filled, would begin to run off, and then, when the lead came out, a hole would be cut, tapping the lowest point of the basin and let the lead out.

This operation to be kept up all along through the operation. The slag running out in a thin stream over

an iron nose into a "buggy" will show metal, when it appears by the different thickness and color. The buggy is simply an inverted pyramid set on legs, it is 12 1/2 in square at the top, and ^{3 in} square at the bottom; it is made of iron and is dragged around with an iron hook. Before using it has to be "swabbed" with a thin layer of fire clay, put onto the iron, when of a milky constituency. The blast is supplied by three tuyeres, one at the back and one on each side driven by a no. 0 Stewart's blower, with a pressure of four oz. of blast on each tuyere, given by 5508 revolutions per minute.

The furnace was all fixed the day before, and a fire started on the inside at half past one P.M., in order to warm up the furnace before using. Three hods of charcoal and four of coke kept the fire going until the next day, when we were ready to put the blast on and begin. Before the ore was put in, some River Copper slag was put into the furnace just to start it going.

Time	Remarks	Time	Remarks
9:35	Blast on	2:40	Rugby 18. Probably good
10.	Slag at tap hole	" "	" 19. Lead
10:30	Fed slag	" 45	" 20. Perhaps lead
10:45	Slag at tap hole	" 55	" 21. " "
11.	Slag running freely	3:15	" 22. " "
11:05	Rugby 1. 22 lbs.	" 25	" 23. Lead
" 15	" 2. 18 1/4 lbs.	" 35	" 24. Poor
" 35	" 3. 28 1/4 lbs.	" 52	" 25. "
" 40	Metal at tap hole.	4:10	" 26. Lead
" 47	Rugby 4. Foul.	" 15	" 27. Lead on top
" 54	" 5. "	" 22	" 28. Foul on top. Separation.
12-12	" 6. "	" 36	Blast off.
" 16	" 7. Steep and dirt.	" 37	Tapped. #29. Foul
" 20	" 8. Lead.	" 42	Blast on. #30. Lead
" 23	Blast on.	" 55	Rugby #31. not good.
" 28	Slag appeared.	5:10	#32. Foul.
" 40	Rugby 9. Foul.	" 11	Blast off. #33. Steep.
" 50	" 10. "	" 15	Tapped.
1-05	" 11. Settled.	" 17	Blast on.
" 20	" 12. Foul out top.	" 21	#34. Lead.
" 35	" 13. Probably settled.	" 25	Blast off.
" 45	" 14. Fairly settled.	" 30	Tapped.
" 50	" 15. Tapped. Lead.	" 36	Blast on. #35 lead visible
" 52	Blast on.	" 53	#36 steep. little lead.
" 58	Slag at tap hole.	" 58	#37 Lead
2-10	Rugby 16. Probably good	6+	Stopped.
" 25	" 17. "	"	"

Feed Door Record.

Time	Charge	Height
mch. 8 P.M. 1-30	3 hods charcoal.	
" "	4 " coke.	
mch. 9 A.M. 9-35	Blast on.	
" 50	1 Coke.	
" 55	1 Coke.	
10 20	1 "	
" 30	2 3/8 Reverse 1 Coke	2 ft.
" 40	25 " "	2 1/4 ft.
" 58	I	2 1/4 "
11-03	F	2 1/2 "
" 15	I	3 "
" 26	I	3 1/4 "
" 39	I	3 1/2 "
" 57	I	3 1/2 "
12-05	I	3 2/3 "
" 30	I	3 3/4 "
" 45	I	3 3/4 "
1-10	I	" "
" 30	III	" "
" 50	II	" "
2-05	III	4 1/2 "
" 29	III	4 "
" 45	III	4 1/4 "
" 52	III	5 "
3-24	III	5 "
4-12	IV	4 1/2 "
" 38	IV	4 1/2 "
5-17	IV	4 1/4 "
" 33	IV	4 1/2 "
5-58	IV	4 3/4 "

Charges

	I.	II.	III.	IV.
Ore	30	30	30	30
Cinder	13	13	13	13
Limestone	1 3/8	1 3/8	1 3/8	1 3/8
Galena	1	2	2	5
Coke	10	8	10	7

To find the amount of coal used.

10 charges of I 100
 6 " " III 60
 1 " " II 58
 5 " " IV 40
 208 lbs

Put in first four hods of coke and three hods charcoal which are equal to $\frac{14}{7}$ 5 lbs coke and $\frac{6}{18}$ 18 lbs charcoal
 208 + 56 = 264 + coke

The slag ran in too thick and viscid a stream to keep molten long, and it did not allow the lead to settle out much inside the furnace, but took it along with it, so as it was thick, the lead did not settle when collected in a buggy outside, but cooled in with the slag.

The table shows that none of the buggies made a complete separation, but had the lead scattered all through the slag. We put charcoal onto the hot slag in the buggies to keep it cold, until it could settle, but it did not do much good.

The furnace was stopped by the babbitt metal melting out of its case on the shaft that ran the blower, then when the front of the furnace was rocked in, the coke was found to be nearly at the top of the shaft. This shows that most of the air was used up near the tuyeres by the coke, and the ore was reduced far above, so that the lead trickled through the hot coals and much ^{was} volatilized in this way. This shows that we had been using too much coke.

Blow down record.

Time	Interval	Charge	Depth	Rise	Remarks
Mar 26 1:45		80 lbs coke			Fire lit. 18 hods of charcoal
Mar 27 9:25		12 1/4 coke	1 1/4		Blast on. used on front
" 33	7 mts.				" " basin add two
" 39	6 "	14 1/2 "	1 1/2 ft.	1/2 ft.	
" 43	4 "	13 3/8 "	1 1/2 "	1/2 "	
" 46	3 "	13 "	2 "	1/2 "	
" 47	1 "				Blast off.
" 56	9 "				on. = 20 hods = 12 lbs
10-18	22 "	14 coke	2 "	1/2 "	
" 33	15 "	I	2 "	1/2 "	leak
" 40	7 "	I	2 "	" "	
" 47	7 "	I	2 1/4 "	" "	
" 52	5 "	V	2 1/2 "	" "	
" 58	6 "	V	2 1/2 "	" "	Dull flame in shaft.
11-05	7 "	VI	3 "	" "	no flame after charge.
" 15	10 "	VI	3 1/4 "	3/4 "	
" 26	11 "	VI	3 1/4 "	3/4 "	
" 36	10 "	VI	3 1/4 "	3/4 "	
" 54	18 "	II	2 3/4 "	1/4 "	Ors =
12-06	12 "	III	3 "	1/2 "	No " " "
" 17	11 "	III	3 "	" "	
" 32	15 "	III	3 "	" "	
" 43	11 "	VII	3 "	" "	
" 55	12 "	VII	3 1/4 "	" "	
1-04	9 "	VII	3 1/2 "	1/2 "	
" 19	5 "	VII	3 1/2 "	3/4 "	
" 24	5 "	VII	3 3/4 "	1/2 "	Began to give charge of things left
" 27	13 "	VIII	4 "	3/4 "	Blow off to run. 2 XI 0
" 31	4 "				Blast off
" 35	4 "				on. 2 VIII 0
" 48	13 "	VIII	3 3/4 "	3/4 "	
2-00	12 "	IX	3 3/4 "	3/4 "	
" 18	18 "	IX	3 1/2 "	1/2 "	
" 30	12 "	IX	3 3/4 "	1/2 "	
" 48	18 "	XI	3 1/2 "	1/4 "	
3-07	19 "	XI	3 "	1/4 "	
" 48	44 "		1 3/4 "		
4-14	26 "	XII			

Ors	I	II	III	IV	V	VI	VII	VIII	IX	XI	XII
Ors											
Gas		30	40	45			40	60	60		
Galena		13 1/2	13 1/4	1			13 1/4				
Lead		13	17 1/2	19 1/2			17 1/2				
Coke	8	10	10	10	10	12	8	8	9	8	10 1/2
Revers Blast	30				40	40					
Lime	1	1 3/8	1 3/4	2			1 3/4				

1:4 1:45 1:6 1:69 1:4 1:35 1:75 1:75 1:7 1:4

Tap Record.

Time	Patrol	Buggy	Remarks
10:51			Slag in sight, running into basin from furnace.
11:27	36		Slag running into Buggy.
" 30	5	1	Clear slag
" 35	5	2	" "
" 41	6	3	" "
" 47	6	4	" " Settled.
" 55	8	5	" "
12--	5	6	" "
" 06	6	—	Lead fumes
" 07	1	7	Settled
" 19	12	8	Not settled
" 33	14	9	" "
" 46	13	10	" "
" 57	11	—	Tapped.
" "	0	11	Not settled.
1-08	11	—	Slag run again
" 16	8	12	" "
" 20	4	13	" "
" 30	10	—	Tapped. Blast off.
" 32	02	14	Settled Blast on
" 40	8	—	Slag appeared
" 44	8	15	" "
2-00	12	16	" "
" 08	8	17	" "
" 15	7	—	Tapped
" 16	1	18	" "
" 23	7	—	Slag ran.
" 37	14	19	Poorly settled
" 48	11	20	" "
3 00	12	21	Tapped.
07	7	—	" "
20	13	—	Slag appeared.
30	10	22	Contains heavy slag
45	15	23	" "
54	9	24	" "
4 03	9	25	" "
10	7	26	" "
20	10	—	Slag disappeared.
25	05	—	Tapped. Blast off
30	05	27	in full.
35	05	—	Tapped
40	05	—	Perout Broken in

The faults of the run were too much coke, slow rate of slag flow and charging, and not tinned. The low state of the coke for first half hour also retarded operations. Below 27. This last, made the lowering of the amount of coke in the charges a doubtful thing at first, but it soon corrected itself but was not appreciated in time, and the reduction in

the ratio of the fuel to other materials from 1 coal to 3 slag at 11:02 clock, to $\frac{12}{243} \frac{1.6}{1.75}$ 1 coal to 8 slag at 2-11:12

two o'clock through steps in the right direction, did not succeed in putting the furnace in good order. A longer run would have fixed this. This was a much better run than the last, the lead all settled in the basin together with a lot of matte, and the slag, that ran into the fugger had no specks of lead in it, though it did not form a cake from which the matte separated, and a sample ^{could be} taken of the slag for analysis. The lead only had some matte on it. There were a foot and a half of coke in the furnace when the front was broken in, from which all slag had been melted out. The basin in front had a large lot of matte in it, from which a sample was taken, and a little lead, the slag was in a good lump, and would have given a good sample, if there had been no reverse slag in it.

The slag was picked over the following day and examined but no sample of slag good enough for analysis found, so the lot was thrown away.

Owing to this mixing of matte and

Slag, no analysis of the slag could be made to compare with the calculated slag. The rich steep of both runs was ground and what passed over a 1/2 in sieve was mostly lead, the remainder was sampled and analysed and thrown away.

Products Steep 312 1/2 lbs holding 10.5 o/s of lead. Slag from first run having globules, and lead chemically combined, 323 1/2 lbs analysing 7.84 o/s of lead, Slag from second run, no globules, 5.1 o/s of lead.

782 lbs lead slag and Reverse - 433 lbs. Reverse. 349 lbs.

312 1/2	323 1/2	349
10.56	7.84	5.1

33.000 + 25.36 + 17.79 = 76.15 lbs

The matte had 18.2 o/s of lead

15.8	2.8
18.2	76.43
2875	

76.43 lbs. of lead in slag and waste products.

The lead in ingots and pieces was 493 7/8 lbs, but this had matte, slag, copper etc amounting to 50.0 lbs, leaving me 437 7/8 lbs of lead.

Lost in slag 76.43 plus the lead shown above gives me 514.3 lbs. of lead accounted for. The rest went up the chimney as lead fume. Lead in agglomerated ore 1604.5

Lead in slag and pieces 514.3

Lead that flew away 90.2 lbs.

Lead fume plus loss by slag equals 1666.6 lbs.

In the blast furnace runs, one man was in charge of the feed door and two men at the tapping door.

As no slag sample could be made I took 13 lbs. of the mixed slag and matte, and fused them under charcoal in a plum bago crucible. To do this I started a fire, in a 12 in by 12 in Rized furnace, with hard coal, and while the coals were still black, placed the crucible on them upside down. As soon as the bottom was warm, the cover was placed on the furnace, until the edges of the crucible were red hot, when the crucible was turned over, on to its bottom and packed in with coal, then I put in the charge of slag etc and put the cover on to the furnace with ashes, to keep the air from getting at the top of the fire. The slag was first mixed with some fine coal dust to help the fusion. This fire was started at one o'clock, at 1:15 the crucible was put in, at two the charge was put in, at four the charge was fusing and at five twenty it was fused and taken

An analysis of the slag gave

SiO ₂	45.13
Al ₂ O ₃ + P ₂ O ₅ + FeO	26.35
P ₂ O ₅ + Al ₂ O ₃	13.09
45.13, 26.29, 13.05	
CaO	9.60
ZnO	3.50
PbO	1.25
MgO	1.72
	<u>100.55</u>
Sulphur	.76
	101.31

The determinations of CaO, ZnO, MgO were made for me by Mr. Powell, who kindly helped me, for I had not the time to make them myself. This fusion goes to show that there was much matte formed, and that the wax can be smelted out from the slag. After all the fusing it is seen there was still some of this troublesome zinc left in the slag, and very likely some in the matte.

All the lead was now collected, consisting of ingots from good takings in second run, lead that had settled in the buggies, and pieces that had been collected in lifting. These were fused, or refined under charcoal in plumbago crucibles. When melted, the slag and dirt are skimmed off from the lead and fused separately. The lead is poured into ingot moulds if clean, but if not, it is poured into a buggy and

the matte or dirt allowed to collect on the top and pounded off when cold, and then the ingot is remelted and cast into ingots of five or ten pounds weight.

This refining also drives off most of the sulphur that has gone into the lead.

The pieces of lead were so irregular in shape, that it was not possible to get all the slag off the cakes that came from the first run. Often I could not get the whole charge into the crucible at first, but had to wait until part had melted, before I got it all in.

The crucibles held nearly sixty pounds of lead, but forty was what I generally put in, as sixty pounds of molten lead are hard to manage when the heat of the furnace is as great as it had to be for this purpose. I used the same furnace that I used in getting my slag sample, and another one measuring 14 in by 14 in.

It took three days, using both furnaces, to do this refining, part of the time in fusing the skimmings (from the crucibles) which were rich in lead.

Furnace No. 2

Time	Interval	Notes	Charge	Remarks
8:50		Fire lit.		March 31, 1876
9:00	10	Crucible in		Furnace 2 14 by 14.
" 10	10	" warm		5 Anthracite - 12 lbs. lbs. charged
" 35	25	Lead in	36 5/8 lbs	Slag Lead
10:25	50	Regains to skin		
1:15	2 hours	Crucible in		Lead 36 5/8
2:30	1:15	Lead in	52 lbs	Ingot Lead 52
3:30	60	Poured		36 5/8
" 35	5	Lead in	36 5/8	Slag Lead. 44
4:40	65	Poured		7
" 45	5	Lead in	44	Ingot Lead. Lead taken 18 1/4 94 1/2 lbs.
5:25	40	" out		
8:40		Crucible in		April 1 st
9:10	30	Lead in	44	Remelting Ingot Remelted 44
10:25	75	" out		31 3/4
" 30	5	Slag in	7 lbs	Slag with little lead
2:55	2:65	" out		Poor Fusion
3:00	5	Matte in	18 1/4	
4:10	70			
4:25	65	Poured		Good heat and fused
9:17		Fire lit		April 4 3 Anthracite 24 72 lbs
" 55	38	Skimmings in	41 5/8	1 Charcoal 6 lbs
11:15	80	Melting		
12:00	1:05	Out		
2:30	30	Lead in	31 3/4	Ingot from skimmings.
4:30	1:20	" out		

Furnace No. 1.

Time	Interval	Notes	Charge	Remarks		
8:55		Fire lit.		March 31. Furnace 1/2 by 1/2		
9:05	10	Crucible in		Coal 7 hods anthracite and		
" 20	15	" - over		one of charcoal. 168 and 6 lbs.		
" 45	25	Lead in	40 lbs	Angot.	40	
10:48	63	" Out			25	
" 50	2	" in	25	Angot.	40 5/8	
12:15	185	" out			47 1/4	
" 20	5	Lead in	40 5/8	Slag.	44 9/8	
1:05	45	" Out			45	
" 10	5	" in	47 1/4	Angot.	20 7/8	
2:00	50	" Out			15 1/4	
" 10	10	" in	44 6/8	Angot.	Lead slag and matte. 278 3/4	
" 45	35	" Out			Furnace? 194 1/2	
" 50	5	" in	45	Angot.	47 3/4	
5:15	145	" Out			44	
8:30		Crucible in		April 1 st .	48	
" 50	20	Lead in	48	Remelting Angot.	54	
10:15	85	" Out			30 1/4	
" 20	5	" in	54	Remelt. Angot	177 1/4 lbs	
11:05	45	Lead out			were remelted	
" 20	15	Matte in	20 7/8		From these	
1:30	130	" out			fusings I	
" 40	10	Slag in	15 1/4		got matte	
		Taken out about 5 o'clock.				Lead and
					Slag.	

Under this central channel is a row of the burners, and under the upper part of the plate are eight burners in four rows, which melt the lead. The lead being melted runs down the channel, and after it has been going a little while, a coating of litharge forms over it, keeping much of the dirt back. A ladle is placed at the lower end to catch the lead, and is kept hot by another burner lamp. The plate is 2 ft. (or by 10 in.) and has to be "rewabbed" before using. About 40 lbs. of lead can be put on at once and when running well, about ten ladles full (weighing $7\frac{1}{2}$ lbs.) can be run in an hour. The lead is kept from the cool air (to bite melting) by a sheet iron cover, which fits over it. This operation took 1.3 minutes per ladle. The amount of lead refined and ready for the next operation was $390\frac{1}{2}$ lbs., minus 48 lbs. making a loss of 441
 $438\frac{1}{2}$ $2\frac{1}{2}$ lbs. The lead analysed 98.95 of fine, by two analyses 98.85 and 99.05.

The gum was smelted along with the matte from the refining, with enough galena to form a sulphide of copper with ^(CuS)

the copper in the scum. As I had not time to analyse the scum, I took it for granted that all the copper not in the matte was in that, and so added galena enough to form Cu₂S with it.

The matte had 24.83 o/o of sulphur, 1.82 o/o of lead, and .024 o/o of silver, 9.53 of copper.

9.53	11.00
<u>15.8</u>	<u>5.2</u>
1.50	5.72 lbs

There were then 4.22 lbs. of copper not in the matte, and let x equal the amount of sulphur wanted, then we have $x : 4.22 :: 32^S : 63.4^Cu$ $x = 2.12$ lbs.

The galena has 20.6 o/o of S, therefore 10.2 lbs. of galena avg wanted $2.06 \frac{2.12}{10.2}$

So, for this fusion, we have 48 lbs of scum 15.8 matte and 10.2 galena. I made two charges of it, and used four hods coal $\frac{24}{96}$ 96 lbs and one hod of charcoal 6 lbs.

At 9.10 Fire lit - 9.30 Crucible in - 10 - Lead in - 11 - Lead out - 12.0 Second charge in - 3.50 charge out.

First charge gave 10 1/2 matte and 2 1/2 lead
Second charge gave 8 1/4 matte and 2 3/4 lead

Making a total of 18 3/4 matte and 4.5 lead
The scum then lost $\frac{4.5}{6.2} \frac{48}{38.8} 9.2$ lbs. of dirt, sulphur etc. The 6.2 lbs came from the galena. In the 9.2 lbs are the slag etc from the galena. These 4.5 lbs were sweated and

gave $39\frac{1}{4}$ lbs of refined lead, so for the next operation I had $390\frac{1}{2} + 39\frac{1}{4} = 429\frac{3}{4}$ lbs of pig lead.

This assayed .197% of silver. The last residue was $5\frac{1}{4}$ pounds but as it was very impure it was left alone.

Zincing

In order to cupel the lead and get the silver out, it is first necessary to concentrate the silver into a smaller lot of lead. I used the Parkes process of zincing as follows, if the lead is melted nearly to driving, and then molten zinc is stirred in, the zinc will take the silver away from the lead, and as the mixture cools the zinc will crystallize and cool on the top, where it can be skimmed off, and the lead left in the pot comparatively poor in silver. Of course the zinc will take very much lead with it, but much can be sweated off. Here I differed from the regular way, when the zinc had been stirred in for ten minutes, I ran it into ingots, and sweated them, the zinc requiring a higher temperature than lead for melting, does not melt, but stays along with some

lead on the iron where it can be scraped off. I melted up 226 $\frac{3}{4}$ lbs of lead in an iron pot (which had previously been thoroughly "swabbed"), to the required point, and put in one per cent of zinc, which I melted in a hessian crucible at a side fire. The zinc was heated, so that when exposed to the air, it burned to zinc white. The lead must be well stirred until the zinc is being put in, or it ^(the zinc) will float on top (being lighter), and not extract the silver.

I then zinced the remainder 203 lbs., as I had the first lot. The first charge filled the pot too well, to be stirred easily.

After this zincing, I treated the whole lot, and zinced twice with 1% of zinc each time, and sweated after each zincing. Adding the zinc in three ways, is better than adding it all at once, because it requires less zinc, and is more effective.

The silver varied as follows:

	Lead	1 st Zincing	2 nd Zinc.	3 rd Zinc	Zinc Cont.
Silver	.197 sps	.0525 sps	.0035 sps	.001 sps	9.7 sps
Amount	12.33 oz	3.09 oz	.195 oz	0.50 oz	9.73 oz

The oz show the amount of silver in the lead after

sweating, the per cents at the same time, also. To get the amount of silver in the pig lead, it was so poor, that I had to take 100 grammes for analysis, to get a button that I could weigh.

1 st Zincing			2 nd Zinc.		3 rd Zinc.	
Time	Interval	Note	Time	Interval	Time	Interval
9:30		Fire lit and lead in	10.		9:15	
11:20	1 hour 50 mts	Zinc in	1.	3 hours	11	1 hour 45 mts
11:35	15 mts.	Charge out	1:40	10 mts.	11-10	10 mts.
11:40	5 "	2 nd Charge in	1:20	10 "	11-15	5 "
1:05	85 "	" Zinc Out	2-	40 "	12:05	50 "
1-15	10 "	" Charge out	2-10	10 "	12-15	10 "

3 Charcoal, 3 coke for melting zinc, and six lbs of bituminous coal were used.

After zincing I had $84\frac{3}{8}$ lbs. of crust, and $35\frac{6}{12}$ zinced lead, which would make only $7\frac{1}{2}$ lb. loss in this operation, that is the lead and zinc and silver in the crust should weigh $85\frac{1}{4}$ lbs, instead of $84\frac{3}{8}$. I had to use the heater for sweating, and do the zincing at the same time, so I could not take the time it took to sweat the ingots all through, as I had to stop sweating often to look after

$$\begin{array}{r} 42\ 9\frac{3}{4} \\ 35\ 6\frac{1}{2} \\ \hline 7\ 3\frac{1}{4} \\ 12\ \text{zinc} \\ \hline 85\frac{1}{4} \end{array}$$

the zincing. For the first twenty ladles full, it took, an average of 7% minutes each.

Distilling. Before the crust can be expelled, the zinc must first be got rid of, and this is done by the distillation of the zinc in plumbago crucibles.

The charge is melted down, and lumps of charcoal put on top, the fire is raised to a good red heat with the cover on, and left for about half an hour, until the charge is well heated up, then the cover is partly taken off, to allow air into the crucible. The oxygen unites with some zinc to form zinc white, but most of this is reduced by the carbon, and zinc and carbonic acid formed, both of which go up the chimney; if any lead should oxidize, it is also reduced, and being less volatile than the zinc, it does not go up the chimney, but goes back into the charge. In this way all the zinc is driven off, and some lead, if the heat is too high. When all the zinc is driven off, the lead in the crucible has a bright look, and colors

show on its surface. The two corner furnaces were used.

Time	Intervals	Furnace No. 1	For distilling
9.55		Fire lit	Piled, 3 rods char-
10-10	15 mts	Crucible in	coal, and five rods
" 55	45 "	Lead in 40 lbs.	of coal, respectively
5.50	Hours 55	Finished	18 and 120 lbs
12.35		Fire lit Furnace #2.	From this I
12.45	10 mts	Crucible in	got 68 1/8 lbs. of
1-15	30 "	Lead same in 44 3/8	lead ready for
5.40	4 hrs. 25	Out, but not done.	cupel, and 4 3/4
10.07		On again next day	lbs. of dirt and
5.30	Thrs. 23	Out 11 hrs. 48 mts.	same most of

which was no good, making the amount driven off 84 3/8
 two 6/8 pounds. This process 73 5/8
 depends on the action of the charcoal, 18 1/2
 and the low point at which zinc volatilizes.

This finished the rich lead, the poor lead ought to have the zinc driven off, but I did not have time to do it, so it had to be given up. In order to cupel my lead, I had to make a cupel. First I ground up some calcined bone

in order to get some bonvash I took
 then 90 parts of bonvash, 5 parts of clay
 and 5 parts of lithage, and mixed them
 when dry, and ^{them} moistened ^{them}. To make one
 cupel, I used 50 lbs. bonvash 2.7 lbs. clay
 and 2.7 lbs. lithage. The holders were
 nearly 1 ft. square, only they had rounded
 corners, and were 1/2 deep. After pounding
 the mixture into the cupel, and drying
 for a few days, I broke the arrangement
 getting it into place. The second cupel,
 made at the same time as the first, was
 found to be too dry and crumbling to
 cut, so the mixture had five parts more
 clay added to it, and was pounded into
 the moulds, when damper than at first.

After drying this two days on a
 steam table, it was cut out, and put
 into place in the cupel furnace.

This one was very hard and good, and
 held its form well. The lowest point in
 the basin, scooped out in the cupel, was
 about 1/2 inch below the top of the ring
 holding it. The fire in the furnace was
 made at quarter past six, and the cupel
 was heated from then until 7, when
 100 lbs of lead were put in an anblast

Product.	Weight of Product.	Per cent of Lead.	Amount of Lead.	Loss of Lead.	Per cent of Silver.	Ounces of Silver in Product.	Loss of Silver in Process.
Galena.	1100 lbs.	61.37	675.07		.095	15.24	
Roasted Ore.	1056 "	58.20	614.59	60.48	.096	14.76	48
Agglomerated.	996.25	60.68	604.52	10.07	.086	12.48	22 1/2
Spode lead.	437.87	—	437.87	166.65	—		
Refined lead.	429.75	98.95	425.24	12.63	.197	12.33	15
Cupel "	68.87	99.03	68.27	2.54	.97	9.73	2.6
Unrefined Pig.	356.50	99.44	354.5	42.27	.001	.05	

The total loss of lead is 675.07 - 422.7 = 252.37 lbs. i.e. 37.38% of the lead has been lost in the whole process.

The total loss of silver is 15.24 - 9.73 = 5.51 oz a loss of 36.15% of the silver. The loss of silver in the zipping 2.55 oz, is not good, and is due to the sample stock, the loss of that silver was very likely in the blast furnace.

The sample was taken from the tops of the cakes from the refining, and the top is richer than the bottom of the mould in silver, so the refined lead shows a richer product than it ought. The slag and residue did not give

any silver when I assayed a few grammes.
 The per cent of lead in the unrefined
 pig is only approximate, it has about two
 pounds of zinc in it.

Coal used in:	Charcoal	Leake	Anthracite	Pittsburgh	Pounds Total	Amount of Coal per pound of substance heated
Roasting				654.87 1/2	1100	59 lbs
Agglomerating				546.62 1/2	1056	57 "
1 st Furnace run	30	308			996.25	77 "
2 nd " "	120	309				
Refining Furnace #1	6		120		651	46 "
" " #2	6		168			
Skimmings	6		72		73 3/8	1.06 "
Slag sample	6		24		13	2.30 "
Smelting Matte	6		96		74	1.37 "
Zincing	18	42		120.00	429.75	44 "
Distilling	18		120		84.75	1.37 "
Total	216	659	600	1321.5		

Therefore 2796.5 pounds of fuel 1321.5
 were used on the ore before cupelling. 600.
 659.
 216
 2796.5